

Corrections to the National Designated Landmark submission

House as restored with second wall let the beauty of the clear redwood shin through and  
Was later stained the grey by the Moores.

At the time the Taylor family took possession of the "Solarhemicyclo" (Wright's blueprint name for the house), only the single double

Door just to the west of the tower was remaining from early years when the Jacobs built it.

Of the three other similarly partitioned glass sections, two were removed by Freiburger and Associates who were later sued for

restoration disasters in both the inside pool and the main window wall not holding water in their respective locations. The replacement pool

was corrected by proper three piece seaming and the window wall was replaced 2 years after the original restored wall had been built.

The final window wall like the second was the only glass in the house which was not triple paned. The extra layer of glass would have badly

Impacted solar gain from an extra reflective surface from the third layer.

There was a section of the original floor left as footing for the replacement window wall. It was melded into the new floor and felt to be too dangerous to support the roof and balcony during an entire floor replacement without that structural support. The new wall was then replaced

From one end to the other while never removing the front structural supports.